

Table des matières

Gen8 - upgrade bios & ILO	3
Fichiers	3

Gen8 - upgrade bios & ILO

Fichiers

- [bios_SP99233.exe](#) ⇒ extraire le fichier `SP99233.exe\ROMPaq Flat Files\CPQJ0613.436`
- [ilo_cp046021.exe](#) ⇒ extraire le fichier `cp046021\ilo4_277.bin`
- Flasher via l'ILO :

ILO 4
Product Manufacturer: Dell

Local user: admin | IP: 192.168.1.100 | ILO 4 Firmware: hp-ilo4-277-000

Firmware Update

Information

Type	Date	Version
I/O	Dec 07 2020	2.77

Firmware Update

I/O Firmware

Obtain the firmware image (.bin) file from the Online ROM Flash Component for HPE iLO 4

- The latest component can be downloaded from <http://www.hpe.com/support/ilo4>.
- This component is also available on the HPE Service Pack.

Server Firmware

The following types of server firmware can also be updated from this page:

- HPE System ROM
- System Programmable Logic Device
- SLOX Chassis Firmware

Server firmware files can be obtained from <http://www.hpe.com/support/ilo4>. For more information, please see the [help file](#).

Local File: Update the firmware by uploading a local file. Note: Navigating away from this page before the upload has completed will prevent the update from starting.

File: Aucun fichier choisi

From: <https://unix-bck.ndlp.info/> - Where there is a shell, there is a way

Permanent link: https://unix-bck.ndlp.info/doku.php/blog:gen8_-_upgrade_bios_ilo?rev=1614848008

Last update: 2021/03/04 09:53