

Table des matières

Gen8 - upgrade bios & ILO	3
Fichiers	3

Gen8 - upgrade bios & ILO

Fichiers

- BIOS (01/22/2018)

[bios_SP99233.exe](#) ⇒ extraire le fichier `SP99233.exe\ROMPaq Flat Files\CPQJ0613.436`

- ILO 2.77(17 Dec 2020)

[ilo_cp046021.exe](#) ⇒ extraire le fichier `cp046021\ilo4_277.bin`

- Flasher via l'ILO ⇒ prise en compte lors du prochain reboot

Firmware Information

Type	Date	Version
ILO	Dec 17 2020	2.77

Firmware Update

ILO Firmware

Obtain the firmware image (.bin) file from the Online ROM Flash Component for HPE iLO 4

- The latest component can be downloaded from <http://www.hpe.com/support/ilo4>.
- This component is also available on the HPE Service Pack.

Server Firmware

The following types of server firmware can also be updated from this page:

- HPE System ROM
- System Programmable Logic Device
- iLO Chassis Firmware

Server firmware files can be obtained from <http://www.hpe.com/support/ilo4>. For more information, please see the help file.

Local File Update the firmware by uploading a local file. Note: Navigating away from this page before the upload has completed will prevent the update from starting.

File: Aucun fichier choisi

Annexes

- https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_671606ca210640bb93ae3b683
- <https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX-2a4f6e276e9d4eac9d3716e50b>

From:
<https://unix-bck.ndlp.info/> - Where there is a shell, there is a way

Permanent link:
https://unix-bck.ndlp.info/doku.php/blog:gen8_-_upgrade_bios_ilo?rev=1614848248

Last update: 2021/03/04 09:57